National Transportation Safety Board NTSB ID: FTW95FA129 Aircraft Registration Number: N9448B FACTUAL REPORT Occurrence Date: 03/02/1995 Most Critical Injury: Minor **AVIATION** Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone **ARDMORE** 73401 0815 CST OK

Airport Proximity: Off Airport/Airstrip
Aircraft Information Summary

Aircraft Manufacturer Model/Series Type of Aircraft

CESSNA 208B Airplane

Direction From Airport:

Distance From Landing Facility:

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

HISTORY OF FLIGHT

On March 2, 1995, at 0815 central standard time, a Cessna 208B, N9448B, was substantially damaged during a forced landing near Ardmore, Oklahoma. The instrument rated commercial pilot suffered minor injuries. The airplane, operating under the callsign Martinaire 633, was owned by Cessna Finance Corporation, of Wichita, Kansas, and operated by Martinaire of Dallas, Texas. Instrument meteorological conditions prevailed for the 14 CFR Part 135 cargo flight.

According to the operator, the airplane departed the Tulsa International Airport (TUL), at 0715 with a payload of 1,300 pounds of cargo, destined for the Ardmore Downtown Executive Airport (1F0). A weather briefing was received and an instrument flight plan filed.

The pilot stated he was cleared for the NDB Runway 35 Approach to Ardmore while level at 5,000 feet. The pilot further stated that as he proceeded from the VOR to the NDB for the procedure turn, the airplane accumulated ice at a rapid rate. The pilot stated that he added maximum available power, as he continued to cycle the wing/strut deicing boots.

The pilot stated that the airplane was configured with flaps up, airspeed at 110 knots when he broke out into visual conditions at approximately 400 feet AGL. The pilot further stated that he was unable to arrest the 400 to 500 fpm rate of descent to hold altitude. The airplane impacted in an open pasture in a nose low attitude. The nose landing gear separated, the mains collapsed, and the cargo pod was crushed.

PERSONNEL INFORMATION

The pilot who is home-based at Tulsa, Oklahoma, stated that he had been on duty since 2130 the previous night, and had flown a total of 4.2 hours during the same duty period. His last training session and check ride were completed on February 24, 1995.

AIRCRAFT INFORMATION

The 1988 model airplane was issued a normal category airworthiness certificate on September 22, 1988. The airplane was certified as a single pilot aircraft, certified for flights into known light to moderate icing conditions. The airplane was not equipped with deicing boots for the nosecap of the cargo pod or the landing gear struts.

A review of the airframe and engine records by the FAA inspector, did not reveal any anomalies, uncorrected maintenance, or overdue airworthiness directives. All of the aircraft's deicing and anti-icing systems were reported as operational prior to the flight. The pilot had not reported any maintenance anomalies prior to the flight; however, during a post-accident interview the pilot

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW95FA129

Occurrence Date: 03/02/1995

Occurrence Type: Accident

Narrative (Continued)

stated that forward visibility through the detachable electric windshield anti-ice panel was inadequate, and his forward visibility was completely obscured by the accumulation of clear ice on the windshield.

A review of the loading of the airplane revealed that at the time of the accident, the airplane was being operated within the prescribed weight and balance limits.

METEOROLOGICAL INFORMATION

The Automatic Weather Observation System (AWOS) weather report for Ardmore for 0700 CST was reported as sky partially obscured, 700 overcast, with a mile and a half visibility in drizzle. Temperature was 26 degrees, with a dew point of 25 degrees. The weather minimums for the NDB Runway 35 approach were 638 feet and 1 mile visibility.

COMMUNICATIONS

The pilot informed the airport manager on the Unicom frequency, that he had the current AWOS weather, and he was executing the NDB Runway 35 approach. The airport manager stated that he informed the pilot that freezing drizzle was present and the pilot acknowledged the transmission. His last radio transmission occurred when the pilot reported "procedure turn inbound" to the Unicom.

WRECKAGE AND IMPACT INFORMATION

The airplane impacted on an open pasture approximately 2 miles south of the approach end of runway 35, and one mile west of the extended centerline. Ground scars were found at the initial point of impact on a measured heading of 155 degrees. Chunks of rime and mixed ice contoured to the shape of several parts of the aircraft were found at the initial point of impact. The nose wheel strut and several other components associated with the nose wheel were found within 20 feet of the initial point of impact.

After sliding for approximately 100 yards, the airplane came to rest on a measured magnetic heading of 330 degrees. All three composite blades separated at the hub. The spinner and hub assembly remained attached to the propeller shaft. The two main landing gears were found pushed aft and up, touching the respective wing strut. The belly cargo pod was crushed up and to the left.

The wing flaps were found extended to 20 degrees. The elevator trim was found in the full nose up position. The engine inertial separator was found in the bypass mode.

ADDITIONAL DATA

The wreckage was released to the owner's representative on March 2, 1995, following completion of the field portion of the investigation.

A teardown of the propeller was performed at the propeller manufacturer's facility. A copy of the examination report is enclosed.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW95FA129

Occurrence Date: 03/02/1995

AVIATION			Occurrence Type: Accident											
Landing Facility/Approach In	formation	•												
Airport Name Airp			Airport	ID:		Airport Elevation Runw Ft. MSL 0			way Used Runway Length		th	Runv	vay Width	
Runway Surface Type:														
Runway Surface Condition:														
Type Instrument Approach: VOR/	TVOR													
VFR Approach/Landing: Forced L	anding													
Aircraft Information														
Aircraft Manufacturer CESSNA			- 1	lodel/S 208B	Series						Serial Number 208B0121			
Airworthiness Certificate(s): Norm	nal		•											
Landing Gear Type: Tricycle														
Homebuilt Aircraft? No						Certified Max Gross Wt.					er of Engines: 1		: 1	
				Engine Manufacturer: Model/Series: P&W PT6A-114									d Power: HP	
- Aircraft Inspection Information														
Type of Last Inspection Da				Date of Last Inspection Time Si				nce Last Insp	Airframe Total Time					
AAIP			12/15	12/15/1994				190 Hours				3	669 Hours	
- Emergency Locator Transmitter (ELT) Information													
ELT Installed? Yes	ELT Operat	ed? No)			ELT	Aided i	n Locating Ad	cident S	ite?				
Owner/Operator Information														
Registered Aircraft Owner			Str	reet Ad	ddress P.O. BO	X 308	3							
CESSNA FINANCE CORP.			City	City							Stat	te	Zip Code	
			Str	WICHITA K									67201	
Operator of Aircraft				COLAC		IATIC	ON PLA	CE, # 2000	ı					
MARTINAIRE INC.				City							Stat	te	Zip Code 75235	
Operator Does Business As:					Operator Designator Code: MT9A								70200	
- Type of U.S. Certificate(s) Held:														
Air Carrier Operating Certificate(s)	: On-demand Air	Taxi												
Operating Certificate: Operator Certificate:														
Regulation Flight Conducted Unde	r: Part 135: Air Ta	axi & Co	ommute	er	•									
Type of Flight Operation Conducted	d: Unknown													
		FACT	UAL R	EPOF	RT - AVIATI	ON							Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW95FA129

Occurrence Date: 03/02/1995

AVIAT	Occurrence Type: Accident												
First Pilot Information													
Name	City					ate	Date of Bir	th	Age				
On File	On File	ile				n File	On File		31				
Sex: M Seat Occupie	n Pilot			(Certifica	ate Num	ber: On Fi	е					
Certificate(s): Flight Instructor; Commercial													
Airplane Rating(s): Multi-engine Land; Single-engine Land													
Rotorcraft/Glider/LTA: None													
Instrument Rating(s): Air													
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Instrument Airplane													
Type Rating/Endorsement	for Accident/Ir	ncident Aircra	ft?			Cı	urrent Bier	nnial Fligh	t Revie	w?			
Medical Cert.: Class 1	Medica	al Cert. Statu	s: Valid Me	dicalno wa	ivers/lim			1			Exam: 12/1	9/199	4
								•					
- Flight Time Matrix	Flight Time Matrix All A/C This Make and Model		Airplane Single Engine	Airplane Mult-Engine	Night		Ins Actual	trument Simulat	ed	Rotorcraft	Glide	r	Lighter Than Air
Total Time	4374	2065	4256	100	21	82	43	5	70				
Pilot In Command(PIC)	4110	2065	4256	100		75	43						
Instructor	1784		1784			20	30	_					
Last 90 Days Last 30 Days	180	180 60	180 60			60 50	2	7	2				
Last 24 Hours	4	4	4			3		2					
Seatbelt Used? Yes	'	ılder Harness			Тс		logy Perfo		<u>_</u>	S	Second Pilot	? No	
	<u> </u>												
Flight Plan/Itinerary													
Type of Flight Plan Filed:	FR												
Departure Point					s	State Airport		irport Identifier		Departure Time		Т	ime Zone
TULSA					0	OK TUL			0730			CST	
Destination State Airport Identifier													
Same as Accident/Incident Location							1F						
Type of Clearance: IFR													
Type of Airspace: Class E													
Weather Information													
Source of Briefing: Flight Service Station													
Method of Briefing:													
FACTUAL REPORT - AVIATION Page 3													

National Transportation Safety Board FACTUAL REPORT

NTSB ID: FTW95FA129

Occurrence Date: 03/02/1995

	AVIATION		Occ	currence	e Type:	Acciden	nt						
Weather Information													
WOF ID	Observation Time	Time Zone	WOF	Elevatio	n	WOF Distance From Accide			lent Site Direction I		Direction Fron	From Accident Site	
	0000			0 Ft. I	MSL				0 NM		0 Deg. Mag.		
Sky/Lowes					0 Ft. AGL			Condition of Light: Day					
Lowest Ce	7	700 Ft. AGL			ility:	1.75	SM Al		neter:	30.00	"Hg		
Temperatu	emperature: -3 °C Dew Point: -4 °C Wind Direction: Density Altitude:							Ft.					
Wind Spee	ed: Light and Variable	Gusts:			Weath	ner Condt	ions at Acci	dent Si	te: Instrume	ent C	onditions		
Visibility (R	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensity	y of Precipit	ation: [Moderate				
Restriction	s to Visibility: Fog												
Type of Precipitation: Freezing Drizzle; Freezing Rain													
Accident Information													
Aircraft Damage: Aircraft Fire:					:				Aircraft Exp	losior	า		
Classificati	on:												
- Injury Su	mmary Matrix	Fatal	Serious	Minor		None	TOTAL						
First Pi	lot				1		1]					
Second	d Pilot												
Studen	t Pilot]					
Flight I	nstructor							1					
Check	Pilot												
Flight E	ngineer												
Cabin A	Attendants												
Other C	Crew												
Passen	igers												
- TOTAL A	ABOARD -				1		1	1					
Other G	Ground	0	0		0		0	1					l
- GRAND	TOTAL -	0	0		1		1	1					l

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: FTW95FA129

Occurrence Date: 03/02/1995

Occurrence Type: Accident

A I					
Δdn	าเท	ictr:	ativ/A	Intor	mation
Aun	1111	II O LI (alive	111101	Hallol

Investigator-In-Charge (IIC)

HECTOR R. CASANOVA

Additional Persons Participating in This Accident/Incident Investigation:

GEORGE J COMBS FAA FSDO OKLAHOMA CITY, OK 73108